

**ARIZONA DEPARTMENT**



**OF CORRECTIONS**

Engineering & Facilities Bureau

## ASP Kingman-Hualapai Unit



Evaluation Of Damage Following Disturbance  
Report Dated 7/7/15

**Michael Landry**

**July 8, 2015**

**Administrator  
Engineering & Facilities Bureau  
Arizona Department of Corrections  
[mlandry@azcorrections.gov](mailto:mlandry@azcorrections.gov)  
602-364-4292**

**Evaluation of damage and adherence to ADOC Physical Plant Standards of ASP-Kingman,  
Hualapai Unit, following disturbance**

**Site visit on July 7, 2015**

**Mr. Landry,**

Michael Casebier (ADOC Construction Project Manager) and Paul Garvin (ADOC Construction Project Manager) arrived on site at 11:00 Tuesday morning. MTC CO IV Yvonne Rydgren provided escort and access to all affected areas on Hualapai Unit. Dorm 1, 3, 4 and 5 were toured, photographed and assessed. Dorm 2 was occupied so it was not toured. Over 300 photographs were taken to document the widespread damage.

Damage begins immediately upon entering the building(s) with the security cameras either having the wires ripped out or the entire camera pulled of the wall. Cameras in any other areas were also destroyed (if accessible) or wires were pulled out to insure they could not function. Most tempered glass windows in doors were broken out. Approximately 70 percent of all windows in control rooms, living areas and other areas were broken out completely or in the case of the tougher windows around control rooms smashed and broken in an attempt to gain access.

Dorm Control Rooms 5, 4 and 3 were destroyed including most of the Fire Alarm panels, and thermostats. Dorm 1 Control was the mostly heavily damaged outside including security bars (3 were bent away from the window and 2 were completely removed). Inmates were unable to gain access to the interior of Dorm 1.

Approximately 40 percent of Case Worker or other outer office areas were ransacked with most windows broken. Ceiling tiles (and in some cases sections of grid ceiling) were occasionally broken.

Living areas were trashed with all cameras destroyed or wiring pulled out.

Inmate telephones were intact (inside the pods) with the exception of Dorm 3 Pod F 3 out of 4 were ripped off the wall.

Restroom facilities in each run had extensive damage with most porcelain toilets, urinals and lavatories (sinks) being broken and in some cases the restroom was completely destroyed. Heavy metal partitions in the showers were removed (with the grab bar still mounted) and were the principle device for inflicting the most damage. Almost every secure door into the individual Pods were bent beyond repair as the partition was used as a battering ram.

As a result of the destruction of restroom plumbing fixtures water and sewage were present in most pod areas. Combined with inmate property and trash were the CRT type inmate televisions which were thrown or dropped on the floor (most flat screens were intact).

Facilities toured showed compliance with ADOC Physical Plant Standards. Although porcelain fixtures are allowed by standards it clear that Stainless Steel would have resulted in far less damage to the restrooms.

Since the heavy privacy panels from the showers were the main source of most destruction they should be removed and replaced with the plastic hanging type that is in the front of the shower.

If possible ADOC Engineering and Facilities would like to inspect the affected areas in Hualapai Unit once repairs are complete before the facility is re-opened.

**Michael D. Casebier**  
**Construction Project Manager**  
**Engineering and Facilities Bureau**  
**1601 W. Jefferson St. M/C 601**  
**Phoenix, Arizona 85007**

**Office: (602) 364-4290**  
**Cell: (623) 432-4328**  
**Fax: (602) 542-2994**

**Paul L. Garvin**  
**Construction Project Manager**  
**Engineering and Facilities Bureau**  
**1601 W. Jefferson St. M/C 601**  
**Phoenix, Arizona 85007**

**Office: (602) 364-4296**  
**Cell: (602) 525-7103**  
**Fax: (602) 542-2994**



# ASPC Kingman – Hualapai Unit






## **PHOTOGRAPHS – (Typical Damage)**

- Dorm #5
- Dorm #4
- Dorm #3
- Dorm #1




Note: See Photo Index for full list of pictures taken at each dormitory. Photos can be viewed on the shared drive; [SHARED\(\\CO-FILE03\)\(K:\)-ASPC-Kingman](#) Hualapai Unit.



## Dormitory # 5






## Dormitory # 4






## Dormitory # 3





## Dormitory # 1



## Damage Assessment Photo Index

Photos By: P. Garvin / M. Casebier

**Dormitory No. 5**

Photo #	Pod	Door #	Remarks
110538-167	-	5D1105A	Dorm #5 Entry
110708-409	-	-	Dorm #5 Entry Corridor
110926-286	-	-	Dorm #5 Entry Corridor
110956-002	-	5D1105C	Control Room
111047-674	-	5D1105C	Control Room
111105-034	-	5D1105C	Control Room
111143-528	-	5D1105C	Control Room
111207-279	-	5D1105C	Control Room
289	-	5D1105C	Control Room
827	-	5D1105C	Staff Restroom - No damage
751	-	5D1105C	Control Room Roof Hatch
449	-	5D1105C	Control Room Desk
717	-	5D1105C	Control Room Desk
840	A	5D1116B	Pod A Entrance
443	A	5D1116B	Pod A Entrance Ceiling
336	A	5D1116B	Pod A
898	A	5D1116B	Pod A
553	A	5D1116B	Ceiling
835	A	5D1116B	Toilet / Shower Area
834	A	5D1116B	Toilet / Shower Area
111	A	5D1116B	Toilet / Shower Area
540	A	5D1117B	Storage Room Door - Broken Vision Panel Glass
008	A	5D1117A	Pod A Rear Door
782	A	5D1117A	Pod A Ceiling
408	B	5D1116A	Pod B Entry Door
458	B	5D1116A	Pod B Corridor Windows & Bent Bars
85	B	5D1116A	Pod B Ceiling
618	B	5D1116A	Toilet / Shower Area
386	B	5D1116A	Toilet / Shower Area - Broken Lavatories
114308-205	B	5D1116A	Toilet / Shower Area - Broken Mirrors and Lavatories
178	B	5D1116A	Toilet / Shower Area - Broken Lavatories
883	B	5D1126A/B	Storage Room Door - Broken Vision Panel Glass
44	B	-	Misc. Paraphernalia
466	B	-	Damaged Security Camera
165	C	5D1127B	Pod C Entrance
285	C	5D1127B	Pod C
92	C	5D1127B	Toilet / Shower Area - Broken Fixtures
899	C	5D1127B	Toilet / Shower Area - Broken Fixtures
492	C	5D1127B	Pod C - Broken Rear Window
791	D	5D1197A	Pod D Entrance Broken Window
832	C	5D1127B	Missing Ceiling Security Camera
363	D	5D1197A	Missing Ceiling Security Camera
490	D	5D1197A	Pod D - Damaged Ceiling Tiles
408	D	5D1197A	Toilet / Shower Area
626	D	5D1197A	Damaged Ceiling Tile (39) and Light Fixture
73	D	5D1138A/B	Pod D - Rear Door / Storage Room Door
820	-	5D1106A	Office Ceiling Vent Damage

**Dormitory No. 4**

Photo #	Pod	Door #	Remarks
122933	-	4D1108A	Dorm # 4 Entrance
546	-	4D1108A	Dorm #4 Entrance
113	-	4D1108A	Dorm #4 Entry Corridor - Missing Security Camera, Bulletin board, HNR Box Damage
664	-	4D1114A	Office
299	-	4D1108D	Office Corridor
542	-	4D1111A	Case Manager Office
187	-	4D1112A	Case Manager Office
145	-	4D1109A	Classroom
579	-	4D1108B	Staff Restroom
258	-	4D1108C	Control Room Entry - Broken Glass
821	-	4D1108C	Control Room
829	-	4D1108C	Control Room - Ceiling Damage
431	-	4D1108C	Control Room - Console
536	-	4D1108C	Control Room - Damaged F/A Annunciator, Thermostat

246	F		Pod F - Entry
614	F		Pod F
74	F		Pod F
959	F		Pod F
443	F		Toilet / Shower Area
932	F		Toilet / Shower Area
293	F		Pod F Rear Area
927	F	4D1115A/B	Pod F Rear / Storage Room Doors
123004	E	4D1147A	"
123010	E	4D1147A	Bent Window Bars
123017	E	"	Missing Security Camera
123041	E	"	Toilet / Shower Area
123051	E	"	Toilet / Shower Area
123101	E	"	Toilet / Shower Area
123112	E	"	Toilet / Shower Area
123121	E	"	Toilet / Shower Area
123144	E	"	Rear Door / Storage Room Door
123152	E	"	Rear Door # 4D1120A Damage
123212	E	"	Rear Door # 4D1120A Damage
123213	E	"	Rear Door # 4D1120A Damage
123126	E	"	Rear Door # 4D1120A Damage
123220	E	"	Rear Door # 4D1120A Damage
123225	E	"	Rear Door # 4D1120A Damage
123236	E	"	Rear Door # 4D1120A Damage
123311	E	4D1147A	View looking
16	D	4D1146B	Pod D - Entry
799	D	4D1146B	Pod D - Entry
226	D	4D1146B	Pod D
798	D	4D1146B	Pod D
629	D	4D1146B	Pod D
359	D	4D1146B	Pod D
165	D	4D1146B	Toilet / Shower Area
209	D	4D1146B	Pod D - Ceiling
895	D	4D1146B	Pod D Rear Area
348	D	4D1146B	Storage Room
386	D	4D1146B	Pod D
312	D	4D1146B	Pod D
123343	C	4D1146A	Door Damage / Vision Panel Glass Broken
123352	C	4D1146A	Door Number
123405	C	"	Interior Window Frame / Broken Glass
123415	C	"	Damaged ceiling tile
123426	C	"	Missing security Camera / Ceiling tile damage
123455	C	"	Toilet / Shower Area
123506	C	"	Toilet / Shower Area
123524	C	"	Toilet / Shower Area
123533	C	"	Toilet / Shower Area
123610	C	"	Pod C Rear Door / Storage Room Door
123625	C	"	Pod C Rear Door / Storage Room Door
123642	C	"	Pod C Ceiling Tiles
123647	C	"	Pod C Ceiling Tiles
123649	C	"	Pod C Ceiling Tiles
483	B		Pod B - Entry
516	B		Pod B - Entry
859	B		Pod B
618	B		Pod B - Ceiling
335	B		Toilet / Shower Area
65	B		Toilet / Shower Area
948	B		Toilet / Shower Area
663	B		Toilet / Shower Area
420	B		Pod B Rear Area
260	B		Pod B Rear / Storage Room Doors
123739	A	4D1145A	Pod A Entry
123749	A	4D1145A	Entry Door Damage
123756	A	4D1145A	Pod A Entry
123805	A	"	Pod A Ceiling
123809	A	"	Missing Security Camera
123835	A	"	Toilet / Shower Area
123849	A	"	Toilet / Shower Area
123858	A	"	Toilet / Shower Area
123916	A	"	Toilet / Shower Area
123927	A	"	Toilet / Shower Area



123937	A	"	Toilet / Shower Area
123952	A	"	Pod A Ceiling
124006	A	"	Pod A Rear Door / Storage Room Door
124013	A	"	Pod A Rear Door / Storage Room Door
124133	A	4D1108B	Staff Restroom
124141	A	4D1108B	Staff Restroom
124153	A	4D1108B	Staff Restroom Ceiling
124207	A	4D1145A	Pod A Entry

### Dormitory No. 3

Photo #	Pod	Door #	Remarks
124507	-		Dorm #3 Entrance
361	-	3D110	Dorm #3 Entrance
284	-		Dorm #3 Entry Corridor
252	-		Office
340	-	3D11...C	Control Room Entry - Broken Windows
765	-		Control Room
452	-		Control Room
899	-		Control Room
757	-		Control Room
28	-		Control Room
426	-		Staff Restroom
277	-		Staff Restroom - Broken Fixtures
878	-		Control Room - Damaged Thermostat/ Fire Alarm Annunciator
124543	-	3D1108B	Caseworker Office Entry
124552	-	3D1108B	Caseworker Office Entry
124606	-	"	Caseworker Office Entry
124614	-	3D1113A	Caseworker Office Entry
124622	-	3D1111A	Caseworker Office Door
124634	-	3D1112A	Caseworker Office
124639	-	3D1112A	Caseworker Office
124655	-	3D1111A	Caseworker Office Door
124707	-	3D1111A	Caseworker Office
124717	-	"	Caseworker Office
124729	-	3D1111A	Caseworker Office Door
124747	-	3D1109A	Classroom
124754	-	3D1109A	Classroom
124803	-	3D11108D	Caseworker Area Door
962	F	3D1147B	Pod F - Entry
556	F	3D1147B	Pod F - Entry Broken Windows
771	F	3D1147B	Pod F - Missing Telephones
31	F	3D1147B	Pod F
236	F	3D1147B	Pod F
468	F	3D1147B	Toilet / Shower Area
246	F	3D1147B	Pod F Rear Area
412	F	3D1147B	Pod F Rear / Storage Room Doors
124828	E	3D1147A	Pod E Doorway
124834	E	3D1147A	Pod E Corridor Windows
124842	E	3D1147A	Ceiling Damage
124848	E	"	Pod E
124905	E	"	Pod E
124918	E	"	Toilet / Shower Area
124930	E	"	Toilet / Shower Area
124941	E	"	Toilet / Shower Area
124957	E	"	Toilet / Shower Area
125006	E	"	Toilet / Shower Area
125021	E	"	Pod E Rear Ceiling
125038	E	"	Pod E Rear & Storage Room Door
125056	E	3B1120B	"
125119	E	3B1120A	Pod E Rear Door
974	D	-	Pod D
202	D	-	Pod D
775	D	-	Pod D
354	D	-	Toilet / Shower Area
12542-791	D	-	Toilet / Shower Area - Ceiling
893	D	-	Pod D Rear Area
673	D	-	Pod D Rear / Storage Room Doors
125224	C	3D1146A	Pod C Door
125227	C	3D1146A	Pod C Corridor Windows
125237	C	3D1146A	Pod C Door & Windows

125249	C	"	Pod C Ceiling & Security Camera
125259	C	"	Pod C Ceiling, Security Camera, Telephones
125312	C	"	Pod C
125345	C	"	Toilet / Shower Area
125355	C	"	Toilet / Shower Area
125408	C	"	Toilet / Shower Area
125426	C	"	Toilet / Shower Area
125434	C	"	Toilet / Shower Area
125445	C	"	Toilet / Shower Area
125502	C	"	Pod C Rear Area
125517	C	"	Pod C Rear Doors
125559	C	"	Pod C Rear Doors
277	B	3D1145A	Pod B Entry
919	B	3D1145A	Damaged Security Camera Cable
84	B	3D1145A	Pod B
193	B	3D1145A	Pod B
136	B	3D1145A	Pod B
329	B	3D1145A	Toilet / Shower Area
673	B	3D1145A	Toilet / Shower Area - Ceiling
381	B	3D1145A	Toilet / Shower Area - Broken Mirror
362	B	3D1145A	Toilet / Shower Area
574	B	3D1145A	Toilet / Shower Area - Broken Fixtures
104	B	3D1145A	Pod B Rear Area
790	B	3D1145A	Pod B Rear / Storage Room Doors
125638	A	3D1145A	Pod A Entrance Door
125641	A	3D1145A	Pod A Entrance Door & Windows
125650	A	3D1145A	Pod A Entrance Door
125659	A	"	Pod A Ceiling, Security Camera, Telephones
125704	A	"	Pod A
125730	A	"	Toilet / Shower Area
125740	A	"	Toilet / Shower Area
125751	A	"	Toilet / Shower Area
125806	A	"	Toilet / Shower Area
125812	A	"	Toilet / Shower Area
125821	A	"	Toilet / Shower Area
125842	A	"	Pod A Ceiling Rear Area
125903	A	"	Pod A Rear Doors
125915	A	"	Pod A Rear Doors
125923	A	"	Pod A looking toward Control Room
130013	A	3D1145A	Pod A Door & Window To Corridor

#### Dormitory No. 1

Photo #	Pod	Door #	Remarks
130408	-	1D1108A	Dorm #1 Entrance
528	-	1D1108A	Dorm # 1 Entrance
656	-	-	Dorm #1 Entry Corridor
652	-	1D1114A	Office
77	-		Caseworker Office Corridor
573	-		Classroom
922	-		Caseworker Office
765	-		Caseworker Office
826	-		Classroom
915	-	1D1108B	Staff Restroom Door
312	-	1D1108B	Staff Restroom
48	-	1D1108B	Staff Restroom
197	-	1D11..C	Control Room Entry - Broken Windows
276	-		Control Room Entry - Broken Windows , Bent Bars
732	-		Control Room
304	-		Control Room
821	-		Control Room
337	-		Control Room Entry - Broken Windows , Bent Bars
367	-		Control Room Entry - Broken Windows , Bent Bars
130454	F	1D1147B	Pod F Door and Windows
130457	F	1D1147B	Pod F Door and Windows
130515	F	1D1147B	Pod F Door
130522	F	"	Pod F Ceiling, Security Camera, Telephones
130535	F	"	Pod F
130555	F	"	Toilet / Shower Area
130559	F	"	Toilet / Shower Area
130612	F	"	Toilet / Shower Area

130625	F	"	Toilet / Shower Area
130640	F	"	Toilet / Shower Area
130646	F	"	Toilet / Shower Area
130700	F	"	Toilet / Shower Area
130711	F	1D1115A	Pod F Rear
130727	F	1D1115B	Pod F Rear Storage Room Door
130736	F	1D1147B	Missing Receptacle Cover plate
130749	F	"	Pod F Rear Storage Room Door
130800	F	"	Pod F Ceiling
130807	F	"	Pod F Ceiling
130846	F	1D1147B	Pod F Door and Windows toward Corridor
488	E	1D1147A	Pod E Entry Door & Windows
372	E	1D1147A	Pod E
710	E	1D1147A	Pod E
941	E	1D1147A	Pod E
592	E	1D1147A	Toilet / Shower Area - Broken/Missing Water Closets
837	E	1D1147A	Toilet / Shower Area - Missing Water Closets / Partitions
380	E	1D1147A	Toilet / Shower Area
747	E	1D1147A	Pod E Rear Area
248	E	1D1147A	Pod E Rear Door
402	E	1D1147A	Pod E Rear Area Broken Window
69	E	-	Storage Room
130916	D	1D1146B	Pod D Door & Window
130928	D	1D1146B	Pod D Door & Window
130939	D	"	Pod D Ceiling, Security Camera, Telephones
130946	D	"	Pod D Ceiling, Security Camera, Telephones
131007	D	"	Pod D
131014	D	"	Ceiling
131036	D	"	Toilet / Shower Area
131045	D	"	Toilet / Shower Area
131055	D	"	Toilet / Shower Area
131110	D	"	Toilet / Shower Area
131120	D	"	Toilet / Shower Area
131132	D	"	Toilet / Shower Area
131200	D	"	Pod D Rear Area
131216	D	1D1125B	Storage Room Door
131241	D	1D1146B	Pod D Broken Exterior Window (Typical)
131256	D	1D1146B	Missing Receptacle Cover plate
131307	D	1D1146B	Water Stain om CMU Wall
466	C	1D1146A	Pod C - Entry Door & Windows
816	C	1D1146A	Pod C - Telephone Bank
379	C	1D1146A	Pod C
537	C	1D1146A	Pod C
171	C	1D1146A	Toilet / Shower Area
687	C	1D1146A	Toilet / Shower Area
208	C	1D1146A	Toilet / Shower Area
975	C	1D1146A	Pod C Rear Area
572	C	1D1146A	Rear Door
750	B	-	Pod B - Entry Door & Windows
820	B	-	Pod B - Entry Door & Windows
523	B	-	Telephone Bank
954	B	-	Missing Ceiling Tiles
952	B	-	Pod B
869	B	-	Pod B
953	B	-	Pod B
639	B	-	Damaged Toilet / Shower Area
557	B	-	Toilet / Shower Area Ceiling
564	B	-	Toilet / Shower Area
245	B	-	Pod B Rear Area
294	B	1D1135A	Rear Door
131400	A	1D1145A	Pod A Entrance Door Head
131408	A	1D1145A	Pod A Windows at Entrance
131433	A	1D1145A	Pod A Entrance Door Head
131441	A	"	Pod A Ceiling, Security Camera
131452	A	"	Pod A Ceiling
131505	A	"	MATV Outlet Damage
131521	A	"	Toilet / Shower Area
131530	A	"	Toilet / Shower Area
131539	A	"	Toilet / Shower Area
131554	A	"	Toilet / Shower Area



131600	A	"	Toilet / Shower Area
131616	A	"	Pod A Rear Area
131632	A	"	Pod A Rear Door / Storage Room Door
131644	A	"	Pod A
131715	A	"	Pod A Entrance Door & Window
131801	-	-	Dorm #1 Exterior
131812	-	-	Dorm #1 Exterior
131823	-	-	Dorm #1 Exterior